

Thermography Report



FLIR0063.jpg

10/23/20, 3:20 PM



FLIR0063.jpg

10/23/20, 3:20 PM



MEASUREMENTS (°F)

Spot	73.3
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94



There were moisture stains on the foundation walls underneath the front porch and the moisture content was elevated. Recommend repair by waterproofing specialist.




There was possible fungal growth on the foundation walls underneath the front porch. Recommend evaluation/repair by mold remediation specialist



The moisture content was elevated on the front right and rear right foundation walls. Recommend repair by waterproofing specialist.

FLIR0047.jpg

10/22/20, 12:24 PM



FLIR0047.jpg

10/22/20, 12:24 PM



MEASUREMENTS (°F)

Spot	68.5
------	------

PARAMETERS


Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94



The moisture content was elevated in the bottom of the wall in the rear left side of the rear basement room. Recommend repair by waterproofing specialist.

FLIR0045.jpg

10/22/20, 12:24 PM



FLIR0045.jpg

10/22/20, 12:24 PM



MEASUREMENTS (°F)


Spot	69.8
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94

FLIR0043.jpg

10/22/20, 12:20 PM



FLIR0043.jpg

10/22/20, 12:20 PM



MEASUREMENTS (°F)

Spot	69.2
------	------

PARAMETERS


Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94



Water was leaking from the bottom of the shower enclosure when the shower was in use. Recommend repair by qualified carpenter.

FLIR0057.jpg

10/23/20, 3:18 PM



FLIR0057.jpg

10/23/20, 3:18 PM



MEASUREMENTS (°F)


Spot	76.0
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94

FLIR0055.jpg

10/23/20, 3:18 PM



FLIR0055.jpg

10/23/20, 3:18 PM



MEASUREMENTS (°F)


Spot	75.7
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94


FLIR0053.jpg

10/23/20, 3:18 PM



FLIR0053.jpg

10/23/20, 3:18 PM



MEASUREMENTS (°F)


Spot	76.3
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94

FLIR0051.jpg

10/23/20, 3:16 PM



FLIR0051.jpg

10/23/20, 3:16 PM



MEASUREMENTS (°F)


Spot	71.9
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94

FLIR0049.jpg

10/23/20, 3:16 PM



FLIR0049.jpg

10/23/20, 3:16 PM



MEASUREMENTS (°F)


Spot	72.7
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94

FLIR0041.jpg

10/22/20, 12:20 PM



FLIR0041.jpg

10/22/20, 12:20 PM



MEASUREMENTS (°F)

Spot	71.1
------	------


PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94




FLIR0039.jpg

10/22/20, 12:20 PM



FLIR0039.jpg

10/22/20, 12:20 PM



MEASUREMENTS (°F)

Spot	72.6
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94


FLIR0035.jpg

10/22/20, 12:19 PM



FLIR0035.jpg

10/22/20, 12:19 PM



MEASUREMENTS (°F)


Spot	71.1
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94

FLIR0033.jpg

10/22/20, 12:19 PM



FLIR0033.jpg

10/22/20, 12:19 PM



MEASUREMENTS (°F)


Spot	69.1
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94

FLIR0031.jpg

10/22/20, 12:19 PM



FLIR0031.jpg

10/22/20, 12:19 PM



MEASUREMENTS (°F)


Spot	71.0
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94

FLIR0029.jpg

10/22/20, 12:19 PM



FLIR0029.jpg

10/22/20, 12:19 PM



MEASUREMENTS (°F)

Spot	70.9
------	------

PARAMETERS

Emissivity	0.95
Refl. temp.	68.0 °F
Distance	8.00 ft
Relative humidity	50 %
Atmospheric temperature	68.0 °F
Transmission	0.94